

Department of Transportation 7277 Perimeter Road South Seattle, WA 98108-3844

**206-296-7380** 206-296-0190 Fax TTY Relay: 711

www.kingcounty.gov/airport

# 2008 OFFSITE DISCHARGE RECONNAISSANCE

#### Section 1. Background Data

#### Structure #:MH-1-E

Inspection Date	6/27/08	Initial Inspection	
Inspection Time	10:40 AM	Inspection #	1
Weather Conditions	Sunny		
Inspector Name(s)	Peter D., Jesse L.	Rainfall (in, last 24h)	0.0
Inspection Participants		Rainfall (in, last 48h)	0.0
KCIA Drainage Basin #	5		
KCIA Outfall #	5		
Tenant Area (as applicable)	FAA Control Tower, NBF	Photos Taken?	⊠ Yes ☐ No

#### Section 2. Discharge Structure Description

Manhole		Other:
Material	⊠ RCP ☐ CMP ☐ HDPE ☐ Steel	☐ PVC ☐ Other:
Shape	⊠ Circular	□Box
Outlet Dimension (in)	Diameter/Dimensions:24"	
Flow Present?	☐ Yes, Estimate Flow ☐ No, <i>Go To Section 5</i>	
Flow Description (if present)	☐ Slow ☐ Moderate ☐ Fast	

### Section 3. Quantitative Characterization

Turbidity (NTU)	
	[대] [10] [10] [14] [10] [10] [10] [10] [10] [10] [10] [10
pH (standard units)	6.75
Temperature (°C)	22.3

## Section 4. Physical Indicators For Flowing Water

Indicator	Check if Present	Description	Relative Severity Index (1-3)
Odor		Sewage Rancid/Sour Petroleum/Gas Sulfide Other:	☐ Faint ☐ Easily Detected ☐ Noticeable from a distance
Color		☐ Clear ☐ Brown ☐ Gray ☐ Yellow ☐ Green ☐ Orange ☐ Other:	☐ Faint colors in sample bottle ☐ Clearly visible in sample bottle ☐ Clearly visible in discharge flow
Turbidity		See Severity	☐ Slight cloudiness ☐ Cloudy ☐ Opaque
Floatables		Sewage (toilet paper, etc) Suds Oil Sheen Other:	☐ Few/slight ☐ Moderate ☐ Obvious
Section 5. I	Physical licators that	Indicators For Flowing/No are not related to flow present?	n-flowing Water Yes ☐ No <i>(if No, go to Section 6)</i>
Indicator	Check if Preser	*	Comments
Structural Damage		Spalling, Cracking, Chippi Corrosion Other:	ing
Deposits/Stai	ns 🛛	☐ Oily ☑ Flow line ☐ Paint ☐ Other:	
Vegetation		☐ Excessive ☐ Inhibited ☐ Other:	
Pool Quality		☐ Odors ☐ Colors ☐ Floatables ☐ Oil Sheen ☐ Suds ☐ Excessive Alga	e
Benthic Grow	th 🔲	☐ Brown ☐ Orange ☐ Green ☐ Other:	
Section 6. (	Overall D	scharge Characterization	
<ul><li>☐ Potential (F</li><li>☐ Suspect (F)</li></ul>	lowing or lowing with	lon-flowing condition with no in Non-flowing condition with two none or more indicators with se rge is occurring)	or more indicators)

If Overall Discharge Characterization is Suspect or Obvious, Conduct Source Investigation Immediately

#### TAXIWAY BRAVO REHAB - WATER QUALITY/EROSION CONTROL MONITORING DATA

Water Quality Data: (Refer to Monitoring Locations)

Date	Time	Weather	Rainfall	Photos Taken	Discharge location	Turbidity (NTU)	pH Value	Temperature (°C)	Comment
10/3/2008	3:45 PM	Rain	0.19	No	3	74.8	6.7	19.5	No discharge from outlet
10/10/2008	3:40 PM	Sunny	0.01	No	3	66	7.8	15.6	No discharge from outlet
10/17/2008	11:20 AM	P.Sunny	0.	Yes	3	73	7.5	17.2	No discharge from outlet
10/23/2008		P.Sunny	0.15	Yes	3	45.3	7.7	16.6	No discharge from outlet
10/31/2008	4:15 PM	Overcast	0.33	Yes	3	62.5	7.7	16.1	Trickle
11/7/2008	12:55 PM	Overcast	2.71	No	3	16	7.6	16.5	
11/14/2008	3:25 PM	Overcast	.0	No	3	56.3	7.4	13.9	No discharge from outlet
11/21/2008	3:40 PM	Overcast	0.01	No	3	17.8	7.4	13.8	No discharge from outlet
11/27/2008	12:40 PM	Sunny	0.02	Yes	3	57.8	7.4	13.4	a 27